

Michael O. Leavitt Governor Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

June 1, 2000

Dan Shepard, President GoldTerra, Incorporated 4088 East Airport Road P.O. Box 783 Price, Utah 84501

Re: Additional Soils Information For Permit Review, GoldTerra Inc, Blue Castle Mine, M/015/077

Emery County, Utah

Dear Mr. Shepard:

On May 16, 2000, Dean Neffler, BLM; Lynn Kunzler and Jared Sorensen, DOGM; and Dan Larsen, EIS; met at the Blue Castle Mine site to evaluate soil quantities available. This evaluation was necessary due to apparent discrepancies between the soil survey contained in GoldTerra's April 26, 2000 notice and the soil amounts projected to be salvaged.

The cost of harvesting and respreading soils could become a significant portion of the required bond, depending on the amounts of soil determined to be available. It is important that this information is submitted to the Division as soon as possible, to allow the Division to complete the review of GoldTerra's April 26, 2000 Notice.

If you have any questions, please contact me at (801) 538-5382 or Lynn Kunzler (801) 538-5310.

Sincerely,

Doug Jensen

Senior Reclamation Specialist Minerals Reclamation Program

ih

cc: Dean Neffler, BLM, Price FO

M15-77-soilsltr